Ministry of Population and Environment (MoPE)

Department of Hydrology and Meteorology (DHM)

Community Based Flood and Glacial Lake Outburst Risk Reduction Project (CFGORRP) Field Visit Report

Team Members: Dr. Rishi Ram Sharma, DG/NPD, DHM/CFGORRP

Mr. Top B. Khatri, NPM/CFGORRP

Mr. Prakash Thapa, Undersecretary, DSCWM

Mr. Mahendra P. Badu, Senior Divisional Engineer, DWIDM

Mr. Kabiraj Sharma, Section Officer, MoFALD

Project field sites, Siraha Udayapur, Mahottari & FCO, Lahan

Overall objective of the field visit/ mission:

- Share and acquaint PEB members/their representatives about the project's interventions and activities under component II in Terai sites
- 1. Interaction with project beneficiaries and district stakeholders on the various interventions undertaken and their opinions and views regarding the ownership and sustainability of the interventions.

Date/Day	Districts/VDCs visited	Persons/Groups interacted with	Description of Field visit Program/Activities
Day 1: 22/06/2016	Janakpur, Sarpallo	Members of	 Left for Janakpur from TIA, Kathmandu.
	VDC, Mahottari	Sankatmochan CDMC,	 Inspected flood control measures, Early
		taskforces, DWIDM	Warning System and Elevated Tube Wells at
		Officials and local	Sarpallo 5, 6, 7 and 8.
		communities	 Observed Evacuation Centre at Sarpallo 5
			 Interacted with members of Sankatmochan
			CDMC and taskforces of Sarpallo 5.
			 Interacted with DWIDM Officials at the site.
			 Moved to Bardibas; overnight stay at Hotel
			Binayak, Bardibas.
Day 2: 23/06/2016	Visited Ratu	Bajarangi and	 After breakfast, the team visted the
	Upstream, Tulsi	Paribartan CDMC	upstream streatch of Ratu rriver at ward
	ward number 6,	members, DSCO-	number 6, Tulsi, VDC, Dhanusa to observe
	Dhanusa District.	Udaypur and local	sediment control measures. Interacted with
	Tulsipur and	communities	Mr. Suresh Koirala, Chair and members of

Key activities carried outbased on the travel itinerary :

Date/Day	Districts/VDCs visited	Persons/Groups interacted with	Description of Field visit Program/Activities
	Jogidaha VDCs,		the gully contoll construction committee on
	Udaypur		how they have been doing and with
			upcoming plans.
			 Inspected flood control measures at
			Mahadev Math, Tulsipur 2, Elevated Tube
			Well and Early Warning System at Bananiya
			Tole and Evacuation Centre at Balu Tole.
			 Interacted with Bajarangi CDMC, Tulsipur 2.
			 Thenafter, travelled to Field Coordination
			Office, Lahan, Siraha. Lunch at Lahan.
			 Moved to Jogidaha VDC, Udaypur from
			Lahan and inspected flood control measures
			and Early Warning System at Mainha,
			Jogidaha 8.
			 Inspected Elevated Tube Well built at the
			premises of VDC Office.
			 Interacted with Paribartan CDMC, Jogidaha
			8 as well as District Soil Consevation Officer,
			Udaypur.
			 Travelled to Gaighat.
			 Overnight stay at Hotel Himalaya, Gaighat.
Day 3:	Due to heavy	Interaction with CDO &	 Held discussion with CDO, SP, NEA
24/06/2016	rainfall, plan to vist	SP, and NEA Udaipur on	authorities on the scope and options of
	Udaypur Gadi could	the options related to	finding an alternate site for radar installation
	not be done.	instalation of radar at	by DHM.
		the highest point in lieu	 Due to incessaant rains and bad weather,
		of Udaipur gadhi.	plan to vist gadi could not be done. Hence
			the team returned to Biratnagr enroute to
			ktm.
			 Returned to Kathmandu via Biratnagar.

2. <u>Major observations/findings made from the field visit/ mission:</u>

Followings are the major achievements till the time of field visit:

- Most of the axctivites and plans that were backlogged in 2015 were found to be completed.
- Some strecthes of launching apron of the embankment were found to be damaged due to the flash flood of 24th May at Balu tole, Tulsipur VDC.

3. Key Recommendations and conclusions:

1) The damaged embankment structures at Balu tole, Tulsipur VDC, Siraha needs to be rectified and brought back to its normal condition.

2) Bioenginnering measures in the embankment strectches needs to be carefully undertaken in order to ensure high survival rates of saplings and enhance greenery.

3) safeguard measures including cleanliness in the vicintiy of strcures needs to be made with some awareness campaigns to esnure long term sustainability of the structres built.

4) As part of government visbility and ownership of the project, hoarding boards needs to clearly depict the name of the implementing agency, DHM. The logo alone of the GON will not suffice.

5) The evacuatiion shelters needs to be enveleoped with a 3 feet wall to ward of waters and other objectives. Currently, the plinth area is open to ground surface.

4. Outputs from the Field Visit/ Mission:

1) Collboarating partners had an first hand view and observation of the various interventions undertaken by the project so far. Valubale suggestions and feedbacks have been received towards ensuring the sustainability of the activites undertaken.

2) The visit also provided an opportunity to interact closely with project beneficiares and stakeholders to have their perception and feelings about the project interventions.

3) The visit also became an important monitoring visit from PMU perspective.

5. Likely Follow-ups that might be necessary after the visit (What Next?):

a) End of third quarter to observe bioengineering works and to followup with MTR recommendations.

6. Major changes observed, if any, since the last field visit made:

- Most of the structural measures that could not be completed in 2015 have been completed.
- Planned replication of CBFEWS in collaboarton with ICIMOD could not be done in Siraha as DHM wanted the EWS to be on a telemetry mode.
- Sediment transport and analysis were resumed from this year.

Date: 28th June 2016.